

RECOMMENDED TIME SCHEDULE & MATERIALS

Lava™ Copings

2 to 3 Days in the lab

MATERIALS REQUESTED

1. Model Work with Pinned Dies, Pinned & Removable Tissue Areas, and Pinned & Removable Adjacent Tooth Areas.
2. You can seal your trimmed dies, but do not paint for any cement space. See 'Prep Diagram' for type preparation, 360° Chamfer
3. Shade
4. Contact Name and Number.
5. Billing Information (Credit Card)
6. For exact pontic placement, include a removable wax up for us to scan.

Contact Ken with any Questions